## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003





REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003






REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003






REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003

Fig.6



REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003

Fig.7



REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003

Fig. 8






Fig.9



REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003



REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003

Fig.13






Fig.14



REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003



REPLACEMENT SHEET 10/605,954 Inventor: Klaus-Jürgen Uhrner Filing Date: 11/10/2003

